

Annexure D

BUILDING SAFETY CERTIFICATE

No. 1541/108

Dated: 02/7/26

It is certified that the existing buildingLALPUR PUBLIC SCHOOL, LALPUR...(name of the building or premises) atLALPUR, RUDRAPUR.....

..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the Block	03	—	—	—	—	—

The building is owned/occupied by....LALPUR PUBLIC SCHOOL..... (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.D.P.W.D., RUDRAPUR (Name of Department/ Govt.) on.....02/07/26..... (date of inspection) in the presence of Mrs. IQBAL AHMAD..... (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from.....02/07/26.. for a period of TWO (02) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. NO
2. —
3. —
4. —

Issued on02/07/26.. atRudrapur..... by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : 

Name : VINOD CHANDRA

Designation : सहायक अभियन्ता

Name & Address of Department Office : ग.प.प.व.ड. लो० नि० वि०
रुद्रपुर (ऊम सिंह नगर)